SEA **Springfield Euro Auto** EXAMPLE SHOP
service@springfield-euro-auto.example

2012 MINI Cooper S at 96,000 mi

WMWSV3C55CT123456

MODEL / CHASSIS	ENGINE	MILEAGE	DRIVETRAIN
Cooper S · R56 Cooper S hardtop	MINI 1.6L Prince four (N12, N14, N16, N18)	96,000 mi	FWD
BUILD MONTH	**REPORT DATE**	**MODE**	**PREPARED FOR**
Not entered (door jamb)	October 27, 2026	Shop	Sample Owner

VIN check: check digit valid; model-year code 'C' = 2012, matches the year entered. The VIN doesn't record the build month. Sample report: synthetic VIN.

1 · SUMMARY

What this car needs, in order

Each item compares this car's mileage with when owners and shops report the part failing. It is not an inspection: our technician decides what the car actually needs.

1
inspection recommended now

1
to plan in the next 30,000 miles · plus 1 factory maintenance item

2
to watch or check at each service

Safety recalls NHTSA lists for this model year (2)

- **18V-248** · Engine cooling · electric auxiliary water pump: The auxiliary water pump's circuit board can overheat, which can cause a fire.
- **23V-337** · Electrical system · footwell control module: Water and road salt can corrode the control module in the driver footwell and short it, which can cause a fire. Applies to cars registered in salt-belt states.

A model-year list, not a VIN check. Repairs are free at a MINI dealer if open. Check this VIN at nhtsa.gov/recalls.

Step 0 · Free: run the VIN at nhtsa.gov/recalls and ask a MINI dealer for a campaign printout, including 18V-248. Read the build month (MM/YY) on the driver's door-jamb label.

Recommended now at the next service — $165

Inspection: check now, while it's cheaper to fix — $165 inspection EXAMPLE

Timing chain, guides and tensioner: Past the range (33,000–78,000 mi, the middle half of 85 owner reports) · if it fails: $1,650–$2,590

Thermostat housing and water pump leaks: Past the range (30,000–64,000 mi, the middle half of 33 owner reports) · if it fails: $1,250–$3,850

Known weak points for this engine, not findings on your car. The inspection shows whether yours has early signs.

Next 12 months up to about 108,000 mi — **$650**

Carbon build-up on intake valves and injectors — **$650**
Any mileage (Direct-injection N14 and N18 engines)
our price EXAMPLE

Within the next 30,000 miles up to 126,000 mi

Nothing else enters its reported range in this window.

Watch inspect at each service, fix on condition, or optional

High-pressure fuel pump (HDP) — **$1,250**
Any mileage (N14 Cooper S/JCW and N18 Cooper S (2011–2012)) · Inspect at each service; fix at the first sign
our price EXAMPLE

Oil leaks: oil pump solenoid, head plug, gaskets — **$420**
Past the range (34,000–55,000 mi, the middle half of 19 owner reports) · Inspect at each service; fix at the first sign
our price EXAMPLE

Recommended now
$165
Springfield Euro Auto prices (example)

Planned through 126,000 mi
$964
Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don’t show it done. Excludes “watch” and optional items.

Prices are Springfield Euro Auto's estimates for typical parts and labor. They don't include tax, shop supplies or disposal fees, and may change after inspection or if part prices change. Not a written repair estimate: Springfield Euro Auto confirms the price and gets your OK before any work.

Bundled jobs are priced together because the labor overlaps. Routine service (oil, brakes, tires) isn't included; factory fluid and spark plug intervals are listed below.

FACTORY MAINTENANCE

Scheduled maintenance from 96,000 mi to 126,000 mi

The maker's normal schedule for this car. Service history isn't known here, so an item is shown at its next interval mark; skip it if the records show it was done.

ITEM	INTERVAL	THIS CAR	OUR PRICE
Brake fluid MINI confirms a 24-month brake fluid interval for these models.	every 2 years	**By time: check the records** [M1]	**$149**

M1. MINI Service Information SI M34 03 13: Brake fluid maintenance service interval (NHTSA) OFFICIAL
https://static.nhtsa.gov/odi/tsbs/2015/MC-10152335-9999.pdf

WHERE 96K SITS FOR EACH WEAK POINT

#	WEAK POINT	REPORTED RANGE	THIS CAR
1	Timing chain, guides and tensioner	33,000–78,000 mi (middle half of 85 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA	Past the range
2	High-pressure fuel pump (HDP)	N14 Cooper S/JCW and N18 Cooper S (2011–2012) OFFICIAL	Any mileage
3	Thermostat housing and water pump leaks	30,000–64,000 mi (middle half of 33 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA	Past the range
4	Carbon build-up on intake valves and injectors	Direct-injection N14 and N18 engines OFFICIAL	Any mileage
5	Oil leaks: oil pump solenoid, head plug, gaskets	34,000–55,000 mi (middle half of 19 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA	Past the range

Colors compare mileage with reported failures, not the car's condition. Red: past the range. Amber: inside or approaching. Green: below, or not listed for a recall.

2 · RECALLS AND BULLETINS

Recalls to check for this 2012 MINI Cooper S

Safety recall repairs are free at MINI dealers. Nothing here can tell whether a recall is open or already done on this VIN; only the official VIN lookup or a dealer can.

Official VIN check (2 minutes)

1. Go to nhtsa.gov/recalls and enter WMWSV3C55CT123456.
2. Note every recall shown as “Recall incomplete” and keep a screenshot.
3. Ask a MINI dealer for a campaign printout; it also lists completed campaigns.

1.6L N12/N14/N16/N18 ("PRINCE") RECALLS WE TRACK

18V-248 · Electric auxiliary water pump can overheat (2011–2012 Cooper S/JCW)

NHTSA lists this model and year: check by VIN

Certain 2011–2012 Cooper S, JCW, Clubman, Countryman, Coupe, Roadster and Convertible turbo models: the electric auxiliary water pump may fail and its circuit board overheat, a fire risk. Free repair. OFFICIAL [14]

☐ VIN checked ☐ Open: booked with dealer ☐ Completed (printout kept)

Other 1.6L N12/N14/N16/N18 ("Prince") recalls we track, not listed by NHTSA for this model and year: 12V-008 (electric auxiliary water pump can overheat (2007–2011 Cooper S/JCW)).

EVERY RECALL NHTSA LISTS FOR THE 2012 MINI COOPER S (2)

RECALL	COMPONENT	WHAT CAN HAPPEN (NHTSA, SHORTENED)
18V-248 1.6L N12/N14/N16/N18 ("Prince") tracked	Engine cooling · electric auxiliary water pump	The auxiliary water pump's circuit board can overheat, which can cause a fire. Details
23V-337	Electrical system · footwell control module	Water and road salt can corrode the control module in the driver footwell and short it, which can cause a fire. Applies to cars registered in salt-belt states. Details

Source: NHTSA recalls API, fetched 2026-10-27 and combined across NHTSA model names: COOPER S. Safety categories (air bags, fire, brakes, stalling, roll-away and loss of control) are listed first; listings whose NHTSA text names another engine, or an aftermarket part, go last. OFFICIAL

SERVICE ACTIONS, BULLETINS AND WARRANTY PROGRAMS

Manufacturer bulletins and warranty programs for this engine are cited on each weak point in section 4, where they apply.

4 · THE 5 WEAK POINTS

Each weak point, one card each


Every figure carries its source. Retailer part numbers are shown only when the retailer lists them for this chassis (R56). Left out because they apply to other models, years, engine sizes or body codes: Timing chain, guides and tensioner (N14, 2007–2010).

1 Timing chain, guides and tensioner

Past the range

Severity: Critical: rare, but can badly damage the engine · 381 mentions in counted NHTSA complaints COMPUTED FROM NHTSA DATA

At 96,000 mi this car is past the reported range (33,000–78,000 mi (middle half of 85 owner complaints that state a mileage)). If the original parts are still fitted, have them checked and plan for them. Range: 33,000–78,000 mi (middle half of 85 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA [1]



Applies to: Mostly N14 Cooper S (2007–2010) and N12 Cooper

WHAT FAILS OFFICIAL [3][2]

The timing chain tensioner can have too little spring force, so the chain rattles at cold start or idle and the guides wear. MINI ran a service action to check the tensioner and chain on N14 engines built 11/2006–5/2009, and a class action extended N14 chain coverage to 7 years/100,000 miles (now ended).

SYMPTOMS

- Rattle for a few seconds at cold start
- Rattle at idle
- Camshaft timing codes

IF IT'S LEFT TOO LONG

A stretched chain can jump and bend the valves.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Fix the rattle early; check whether service action code 61 is done.

ESTIMATED REPAIR COST

Chain, guides and tensioner at an independent shop (forum-reported quotes)	**Our price is in the plan above** ask us for a written quote
Owner-reported repair bills in NHTSA complaints (n=32)	**$1,650–$2,590** COMPUTED FROM NHTSA DATA [1] reported range for the bill after a failure

Where the numbers come from: Fix early: quotes owners reported on North American Motoring, $1,200–$1,400 at independent shops in older threads [17] and about $2,100 for a Countryman in 2023 [18]; dealers quoted $1,400–$4,000. RepairPal's all-years Mini Cooper estimate is higher, $2,491–$3,426 [19]. If it fails: computed from 32 NHTSA owner complaints that quote a repair bill for this problem (middle half of the bills; median $2,120). Examples: ODI 11114985, 10766294, 10523361, 10512949. Owner-reported, often dealer prices; not shop quotes.

PARTS FOR R56

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- Timing chain or tensioner replaced?
- Service action 61 done?
- Any cold-start rattle?

2 High-pressure fuel pump (HDP)

Any mileage

Severity: High: overheating, stalls, limp mode or a big bill · 51 mentions in counted NHTSA complaints
COMPUTED FROM NHTSA DATA

Reports cover a wide mileage span (N14 Cooper S/JCW and N18 Cooper S (2011–2012)), so mileage doesn't say much here. Range: N14 Cooper S/JCW and N18 Cooper S (2011–2012) OFFICIAL [4][5]

WHAT FAILS OFFICIAL [4][5]

The high-pressure fuel pump can fail and cause sudden loss of power or a no-start with a check-engine light. MINI extended HDP coverage to 10 years/120,000 miles on N14 cars (class action) and on early N18 cars; most of that coverage has now ended.

SYMPTOMS

- Loss of power while driving
- Long crank or no start
- Check-engine light with fuel pressure codes (P0087/P0089)

IF IT'S LEFT TOO LONG

The car can lose power suddenly in traffic.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Check the VIN for remaining coverage; replace a failing pump promptly.

ESTIMATED REPAIR COST

Check remaining coverage first	**Our price is in the plan above** ask us for a written quote
Pump and labor at an independent shop	**$930–$1,780** SHOP/RETAILER [11] reported range for the bill after a failure

Where the numbers come from: Retailer repair guide: parts $350–$700 plus shop labor $575–$1,075.

PARTS FOR R56

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- HPFP replaced?
- Any loss-of-power events?

3 Thermostat housing and water pump leaks

Past the range

Severity: High: overheating, stalls, limp mode or a big bill · 166 mentions in counted NHTSA complaints COMPUTED FROM NHTSA DATA

At 96,000 mi this car is past the reported range (30,000–64,000 mi (middle half of 33 owner complaints that state a mileage)). If the original parts are still fitted, have them checked and plan for them. Range: 30,000–64,000 mi (middle half of 33 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA [1]



Applies to: N12/N14/N16/N18 engines

WHAT FAILS OFFICIAL [6][7]

The plastic thermostat housing (N18) and the mechanical water pump leak coolant. MINI extended thermostat coverage to 10 years/120,000 miles on 2014–2016 N18 cars and water pump coverage to 7 years/84,000 miles; most windows have ended.

SYMPTOMS

- Coolant smell or drips
- Low coolant warning
- Overheating

IF IT'S LEFT TOO LONG

Overheating can warp the cylinder head.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Replace leaking parts early; check the VIN for any remaining coverage.

ESTIMATED REPAIR COST

Thermostat replacement (average estimate)	**Our price is in the plan above** ask us for a written quote
Owner-reported repair bills in NHTSA complaints (n=12)	**$1,250–$3,850** COMPUTED FROM NHTSA DATA [1] reported range for the bill after a failure

Where the numbers come from: Computed from 12 NHTSA owner complaints that quote a repair bill for this problem (middle half of the bills; median $2,410). Examples: ODI 10767526, 10606333, 10481465, 10441031. Owner-reported, often dealer prices; not shop quotes.

PARTS FOR R56

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- Thermostat or water pump replaced?
- Any coolant loss?

---

4 Carbon build-up on intake valves and injectors

Any mileage

Severity: Medium: leaks and wear · 13 mentions in counted NHTSA complaints

COMPUTED FROM NHTSA DATA

Reports cover a wide mileage span (Direct-injection N14 and N18 engines), so mileage doesn't say much here. Range: Direct-injection N14 and N18 engines OFFICIAL [8]

WHAT FAILS OFFICIAL [8]

Carbon deposits build up on the intake valves and injector tips of these direct-injection engines. MINI says this is linked to fuel quality and is not a defect; it recommends Top Tier fuel and its fuel additive. Heavy deposits need a walnut-blast cleaning.

SYMPTOMS

- Hesitation or stumble on acceleration
- Misfire codes
- Poor fuel economy

IF IT'S LEFT TOO LONG

Misfires and rough running get worse over time.

IS IT WORTH DOING EARLY? OUR ESTIMATE

ESTIMATED REPAIR COST

Walnut-shell blasting (forum-reported: about $350 at independent shops, $800–$900 at dealers)	**Our price is in the plan above** ask us for a written quote
Same job	**$350–$900** FORUM/BLOG [16] reported range for the bill after a failure

Where the numbers come from: Owners on North American Motoring [16] put walnut-shell blasting near $350 at independent MINI shops and $800–$900 or more

Use Top Tier fuel; clean the intake valves when misfires start.

at dealers. The posts are several years old, so today's quotes may be higher.

PARTS FOR R56

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- Intake valves ever cleaned?
- Fuel used?

5 Oil leaks: oil pump solenoid, head plug, gaskets

Past the range

Severity: Medium: leaks and wear · 89 mentions in counted NHTSA complaints

COMPUTED FROM NHTSA DATA

At 96,000 mi this car is past the reported range (34,000–55,000 mi (middle half of 19 owner complaints that state a mileage)). If the original parts are still fitted, have them checked and plan for them. Range: 34,000–55,000 mi (middle half of 19 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA [1]



Applies to: N16 and N18 engines (built to 1/2013)

WHAT FAILS OFFICIAL [9][10]

Oil can leak from the oil pump volume control solenoid valve; oil can travel along the harness toward the engine computer. On N16 engines a cylinder-head sealing plug below the vacuum pump was not tightened enough at the factory.

SYMPTOMS

- Oil drips under the engine
- Burning-oil smell
- Oil in electrical connectors

IF IT'S LEFT TOO LONG

Oil in the harness can damage the engine computer.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Fix leaks early; check the solenoid connector for oil.

ESTIMATED REPAIR COST

Labor only, 0.5 h MINI warranty time	**Our price is in the plan above** ask us for a written quote
Owner-reported repair bills in NHTSA complaints (n=8)	**$980–$3,600** COMPUTED FROM NHTSA DATA [1] reported range for the bill after a failure

Where the numbers come from: Estimate: MINI warranty labor time of 0.5 h (bulletin [10]) × $100–$160/h independent-shop labor rate [13]. Parts are extra unless stated; check the VIN for open warranty coverage first. (Retorquing the head sealing plug.) Computed from 8 NHTSA owner complaints that quote a repair bill for this problem (middle half of the bills; median $2,220). Examples: ODI 10481465, 10469543, 10552767, 10515850. Owner-reported, often dealer prices; not shop quotes.

PARTS FOR R56

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- Any oil leaks?
- Oil found in connectors?

5 · ALSO REPORTED, NOT RANKED

Other themes in 1.6L N12/N14/N16/N18 ("Prince") owner complaints

Every NHTSA complaint theme with 10 or more counted reports is either a weak point above or explained here.

THEME	COMPLAINTS	WHY IT ISN'T A WEAK POINT
Electric auxiliary water pump / fire	205	Covered by recalls 12V-008 / 18V-248 (auxiliary water pump circuit board can overheat); check they are done.
Stalling / loss of power	197	Mixed causes; often the high-pressure fuel pump or timing chain.
Turbo	109	Turbo failures on N14/N18 Cooper S; MINI bulletins point to oil supply restriction. Not one of the five items above.

How this report is built

Inputs. VIN, model year, model, mileage and build month (if entered). Model and engine are checked with NHTSA's vPIC decoder.

Mileage positions. Below: more than 10,000 miles before the reported range. Approaching: within 10,000. Inside: in the range, or past the start of an open-ended range. Past: beyond the top of the range. These bands are our rules, not an industry standard.

The plan. Critical items inside or past their range go first; high-severity items follow, and jobs that share labor are bundled. At most three jobs land in “Recommended now”. Leaks that are cheap to watch are fixed on condition; inspections are asked for at each service.

Costs. Published independent-shop ranges from shop quotes, retailer prices and owner reports. Shop prices come from the issuing shop. The worst-case cost of every item failing is not shown: it isn't an expected cost.

Labels. `OFFICIAL` NHTSA/BMW documents · `SHOP/RETAILER` parts prices and shop articles · `FORUM/BLOG` owner forums and blogs · `COMPUTED FROM NHTSA DATA` our analysis of NHTSA data · `OUR ESTIMATE` ours.

NHTSA complaint data. Pulled Oct 27, 2026 from NHTSA's complaints API for All complaints for R55–R61 nameplates in the listed years (2014-on hardtops use a different engine and are excluded): 1,980 complaints. We pooled every complaint NHTSA files under these model names and years; where a nameplate also came with another engine or powertrain, a few complaints may be about it. Themes are keyword matches on the complaint text.
`COMPUTED FROM NHTSA DATA`

THEME	COMPLAINTS	IN THIS REPORT
Timing chain rattle	381	Item 1
Electric auxiliary water pump / fire	205	Also reported
Stalling / loss of power	197	Also reported
Coolant / thermostat / water pump	166	Item 3
Turbo	109	Also reported
Oil leak	89	Item 5
High-pressure fuel pump	51	Item 2
Carbon / intake valves	13	Item 4

Limits: complaints are self-reported and not adjusted for cars sold; keyword matching over- and under-counts; owners rarely file safety complaints about oil seeps, so leaks look rarer than they are.

SOURCES

1. NHTSA owner complaints for 2007–2013 Cooper / Cooper S / JCW hardtop, 2008–2014 Clubman, 2009–2015 Convertible, 2011–2016 Countryman, 2013–2016 Paceman, 2012–2015 Coupe and Roadster, pulled Oct 27, 2026 (ODI numbers in the cost notes) `OFFICIAL`
https://www.nhtsa.gov/report-a-safety-problem#complaints

2. MINI USA / BMW NA SI M01 07 16: N14 engine timing chain and tensioner: limited warranty extension to 7 years/100,000 miles (class action) (2016-08-01), filed with NHTSA `OFFICIAL`
https://static.nhtsa.gov/odi/tsbs/2016/MC-10147574-9999.pdf

3. MINI USA / BMW NA SI M11 04 13: Service Action: N14 engine check timing chain tensioner and timing chain (built 11/2006–5/2009) (2014-01-01), filed with NHTSA `OFFICIAL`
https://static.nhtsa.gov/odi/tsbs/2014/MC-10147957-9999.pdf

4. MINI USA / BMW NA SI M01 04 19: Class action settlement: N14 high-pressure fuel pump (HDP) service benefit, 10 years/120,000 miles (2020-01-01), filed with NHTSA `OFFICIAL`
https://static.nhtsa.gov/odi/tsbs/2020/MC-10171506-9999.pdf

5. MINI USA / BMW NA SI M01 01 16: N18 engine high-pressure fuel pump (HDP): limited warranty extension to 10 years/120,000 miles (built to 2/29/2012) (2016-07-01), filed with NHTSA `OFFICIAL`
https://static.nhtsa.gov/odi/tsbs/2017/MC-10146720-9999.pdf

6. MINI USA / BMW NA SI M01 02 18: N18 thermostat with thermostat housing: limited warranty extension to 10 years/120,000 miles (2014–2016 models) (2019-04-01), filed with NHTSA OFFICIAL
https://static.nhtsa.gov/odi/tsbs/2019/MC-10160229-9999.pdf

7. MINI USA / BMW NA SI M01 12 16: Engine mechanical water (coolant) pump: limited warranty extension to 7 years/84,000 miles (2016-12-01), filed with NHTSA OFFICIAL
https://static.nhtsa.gov/odi/tsbs/2016/MC-10146799-9999.pdf

8. MINI USA / BMW NA SI M13 01 15: N18: MINI fuel additive (carbon deposits on intake valves and injectors) (2015-03-01), filed with NHTSA OFFICIAL
https://static.nhtsa.gov/odi/tsbs/2015/MC-10147699-9999.pdf

9. MINI USA / BMW NA SI M11 01 12: N16 and N18 engine: engine oil leak (oil pump volume control solenoid valve) (2015-02-01), filed with NHTSA OFFICIAL
https://static.nhtsa.gov/odi/tsbs/2015/MC-10147108-9999.pdf

10. MINI USA / BMW NA SI M11 04 14: N16 engine: oil leak from cylinder head sealing plug (5 FRU labor allowance) (2014-11-01), filed with NHTSA OFFICIAL
https://static.nhtsa.gov/odi/tsbs/2014/MC-10148441-9999.pdf

11. Go-Parts: P0089 fuel pressure regulator / HPFP guide, MINI Cooper S 2007–2013 1.6L N14 (via search extract Oct 27, 2026) SHOP/RETAILER
https://www.go-parts.com/garage/obd-p0089-mini-cooper-s-2007-2013-1-6l-n14

12. YourMechanic: MINI Cooper Paceman thermostat replacement estimate (via search extract Oct 27, 2026) SHOP/RETAILER
https://yourmechanic.com/estimates/mini/cooper-paceman/thermostat-replacement

13. Tekmetric: average auto repair labor rates by state, 2026 SHOP/RETAILER
https://tours.tekmetric.com/answers/average-auto-repair-labor-rates-by-state-2026

14. NHTSA recall records: 12V-008 and 18V-248 (electric auxiliary water pump), checked Oct 27, 2026 OFFICIAL
https://www.nhtsa.gov/recalls?nhtsaId=12V008000

16. North American Motoring forum: walnut-blasting threads, via search extract Nov 9, 2026 FORUM/BLOG
https://www.northamericanmotoring.com/forums/stock-problems-issues/305666-do-you-walnut-blast-how-often.html

17. North American Motoring forum: "Timing Chain Replacement - Expected Cost" and related threads, via search extract Nov 9, 2026 FORUM/BLOG
https://www.northamericanmotoring.com/forums/stock-problems-issues/326098-timing-chain-replacement-expected-cost.html

18. North American Motoring forum: "Current pricing on Timing Chain replacement", via search extract Nov 9, 2026 FORUM/BLOG
https://www.northamericanmotoring.com/forums/1st-gen-countryman-r60-talk-2010-2015/366346-current-pricing-on-timing-chain-replacement.html

19. RepairPal estimator: Mini Cooper timing chain replacement (all years), via search extract Nov 9, 2026 SHOP/RETAILER
https://repairpal.com/estimator/mini/cooper/timing-chain-replacement-cost

This report contains no affiliate links; retailer prices are quoted as price sources only. Found an error? Email hello@repairahead.com.

PLEASE READ

Important

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN.

Informational only. This report is not a mechanical inspection, a diagnosis, or professional, legal or financial advice. It was issued by Springfield Euro Auto using RepairAhead data; the inspection findings and prices are the shop's.

Reported ranges and estimates, not predictions

Failure mileages are reported ranges compiled from public owner complaints, manufacturer bulletins, recalls and repair-shop reports. Costs are estimates. Parts can fail earlier, later or not at all, and other problems can occur. Statistics from owner complaints describe past reports to NHTSA; NHTSA has not reviewed or endorsed this analysis.

Safety issues go to a dealer

If you notice overheating, a burning or fuel smell, smoke, a brake-assist problem, stalling or loss of power, pull over when it's safe and contact a MINI dealer or qualified shop. Safety recall repairs are free at MINI dealers. Confirm recalls for this VIN at nhtsa.gov/recalls.

No warranty

Provided “as is”, without warranties of any kind, under the Terms of Use at repairahead.com/terms.

Trademarks and independence

Not affiliated with BMW AG or MINI USA. MINI and model names are trademarks of BMW AG, used only to identify vehicles.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN.