SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

TECHNICIAN WORKSHEET · 4.3L 3UZ-FE V8
RA-LEXUZ-123456-20261028

2004 Lexus SC 430 · UZZ40 SC 430 (4.3L V8) · RWD

JTHFN48Y740123456

ODOMETER IN	DOOR-JAMB BUILD (MM/YY)	RO #	TECHNICIAN / DATE
110,000			

A · RECALLS AND CAMPAIGNS TO VERIFY (DEALER PRINTOUT OR NHTSA.GOV)

19V-741 · Air bags · frontal (replacement inflator) ☐ Open ☐ Done ☐ N/A

B · INSPECTION POINTS, IN PLAN ORDER

1. Timing belt and water pump replacement

Now · Past the range (Every 90,000 miles or 9 years, water pump with the belt)

Check the timing belt sticker and records ☐ OK ☐ Watch ☐ Fix

Look for coolant seep at the lower timing cover ☐ OK ☐ Watch ☐ Fix

Belt: recorded / unknown

Parts (UZZ40): Ask your parts supplier for the OE part number for this VIN.

2. Electronic throttle body fault (limp mode)

Watch · Any mileage (2003 GS 430, LS 430 and SC 430 were covered by campaign 3LF)

Scan for throttle-control codes ☐ OK ☐ Watch ☐ Fix

Check the VIN for campaign 3LF ☐ OK ☐ Watch ☐ Fix

Scan for: P2111, P2112, P2118, P2119

Parts (UZZ40): Ask your parts supplier for the OE part number for this VIN.

3. In-tank fuel pump failure (stall, no restart)

Watch · Any mileage (Owner complaints, mainly 2004 LS 430)

Fuel pressure test ☐ OK ☐ Watch ☐ Fix

Scan for lean codes ☐ OK ☐ Watch ☐ Fix

Fuel pressure: in spec / low

Scan for: P0171, P0174, P0230

Parts (UZZ40): Ask your parts supplier for the OE part number for this VIN.

FACTORY MAINTENANCE

Not on this report for this car. Check the service records and the maker's schedule (brake fluid, spark plugs, coolant, transmission fluid). ☐ Records checked ☐ Due ☐ Quoted

C · ALSO REPORTED FOR THE 4.3L 3UZ-FE V8, QUICK CHECKS

- **Air bags** (106 complaints): Takata air bag inflator recalls; not an engine fault. Check the VIN.

WHAT TO SAY AT THE COUNTER (ADVISOR)

1. Timing belt and water pump replacement
These V8s use a rubber timing belt that must be changed on schedule. At 110,000 mi it is due, unless the records show it done. Our price is $1,480, before tax and shop supplies.
Ask: have you noticed coolant seep at the water pump behind the timing covers?

Adjust after the inspection. The report is not a diagnosis or a guarantee, so say what the technician found, not what the report predicts.

NOTES FOR THE ADVISOR

Record findings here (OK / Watch / Fix and measurements); the advisor adjusts the quote before the handout is printed or sent.

Reference only. Follow Lexus repair procedures and your shop's judgment.