SEA
Springfield Euro Auto EXAMPLE
SHOP
service@springfield-euro-auto.example

2004 Volkswagen Jetta at 165,000 mi

3VWSR69MX4M123456

MODEL / CHASSIS	ENGINE	MILEAGE	DRIVETRAIN
Jetta · Mk4 Jetta GLS TDI sedan, 5-speed manual (BEW)	Volkswagen 1.9L TDI four-cylinder diesel (and the 2.0L PD in the Passat)	165,000 mi	FWD
BUILD MONTH	**REPORT DATE**	**MODE**	**PREPARED FOR**
Not entered (door jamb)	October 28, 2026	Shop	Sample Owner

VIN check: check digit valid; model-year code '4' = 2004, matches the year entered. The VIN doesn't record the build month. Sample report: synthetic VIN.

1 · SUMMARY

What this car needs, in order

Each item compares this car's mileage with when owners and shops report the part failing. It is not an inspection: our technician decides what the car actually needs.

2
jobs recommended now

0
to plan in the next 30,000 miles · plus 1 factory maintenance item

3
to watch or check at each service

Safety recalls NHTSA lists for this model year (2)

- **07V-063** · Brake lights · brake light switch: The brake lights can stop working or stay on, so drivers behind may get no warning when the car brakes.
- **04V-586** · Diesel fuel system · high-pressure pump fastener: Diesel fuel can leak, and a leak near a source of ignition can start a fire.

A model-year list, not a VIN check. Repairs are free at a Volkswagen dealer if open. On a car over 15 years old, ask the dealer whether a newer recall is still repaired free. Check this VIN at nhtsa.gov/recalls.

Step 0 · Free: run the VIN at nhtsa.gov/recalls and ask a Volkswagen dealer for a campaign printout, including 04V-586, 07V-063. Read the build month (MM/YY) on the driver's door-jamb label.

Recommended now at the next service — $1,615

Timing belt, tensioner and water pump — $1,450

Past the range (80,000 mi on the 2004–2006 BEW, BRM and BHW (VW figure as quoted by TDI parts specialists and VW customer care); 100,000 mi on the ALH once the 2003-updated belt and roller are fitted (earlier ALH parts: 40,000–80,000 mi). Overdue if there is no record) · if the records don't show it done

our price EXAMPLE

Inspection: check now, while it's cheaper to fix — $165

Clutch and dual-mass flywheel (manual cars): Long past the range (20,200–76,500 mi, the middle half of 50 owner reports) · if it fails: $1,685–$2,650

Camshaft lobe and lifter wear (2004–2006 PD engines): Past the range (70,100–100,000 mi, the middle half of 12 owner reports) · if it fails: $2,900–$4,500

The ones long past their range may already be fixed: we check the records first.

Known weak points for this engine, not findings on your car. The inspection shows whether yours has early signs.

inspection EXAMPLE

Next 12 months up to about 177,000 mi

Nothing scheduled here.

Within the next 30,000 miles up to 195,000 mi

Nothing else enters its reported range in this window.

Watch inspect at each service, fix on condition, or optional

Turbo vanes, boost control and MAF (loss of power) — $165

Long past the range (42,000–81,000 mi, the middle half of 21 owner reports) · may already be fixed at this mileage: we check the records first · Inspect at each service; fix at the first sign

our price EXAMPLE

Intake manifold and EGR clogged with soot — Ask us for a quote

Long past the range (24,000–68,500 mi, the middle half of 16 owner reports) · may already be fixed at this mileage: we check the records first · Ask for this check at every service

Glow plugs and glow plug control — $900

Any mileage (No clear mileage pattern: only 7 owner complaints state a mileage) · Inspect at each service; fix at the first sign

our price EXAMPLE

Recommended now

$1,615

Springfield Euro Auto prices (example)

Planned through 195,000 mi

$1,764

Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don’t show it done. Excludes “watch” and optional items.

Prices are Springfield Euro Auto's estimates for typical parts and labor. They don't include tax, shop supplies or disposal fees, and may change after inspection or if part prices change. Not a written repair estimate: Springfield Euro Auto confirms the price and gets your OK before any work.

Bundled jobs are priced together because the labor overlaps. Routine service (oil, brakes, tires) isn't included; factory fluid and spark plug intervals are listed below.

FACTORY MAINTENANCE

Scheduled maintenance from 165,000 mi to 195,000 mi

The maker's normal schedule for this car. Service history isn't known here, so an item is shown at its next interval mark; skip it if the records show it was done.

ITEM	INTERVAL	THIS CAR	OUR PRICE
Brake fluid Every 2 years regardless of mileage.	every 2 years	**By time: check the records** [M1][M2]	**$149**

M1. Bentley Publishers: VW 2001 Jetta, Golf, GTI factory maintenance schedule SHOP/RETAILER
https://bentleypubs.atlassian.net/wiki/spaces/tech/pages/437453493

M2. Bentley Publishers: VW 2006 Jetta, Rabbit, GTI factory maintenance schedule SHOP/RETAILER
https://bentleypubs.atlassian.net/wiki/spaces/tech/pages/437453575

WHERE 165K SITS FOR EACH WEAK POINT

#	WEAK POINT	REPORTED RANGE	THIS CAR
1	Timing belt, tensioner and water pump	80,000 mi on the 2004–2006 BEW, BRM and BHW (VW figure as quoted by TDI parts specialists and VW customer care); 100,000 mi on the ALH once the 2003-updated belt and roller are fitted (earlier ALH parts: 40,000–80,000 mi). Overdue if there is no record SHOP/RETAILER	Past the range
2	Clutch and dual-mass flywheel (manual cars)	20,200–76,500 mi (middle half of 50 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA	Long past the range
3	Camshaft lobe and lifter wear (2004–2006 PD engines)	70,100–100,000 mi (middle half of 12 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA	Past the range
4	Turbo vanes, boost control and MAF (loss of power)	42,000–81,000 mi (middle half of 21 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA	Long past the range
5	Intake manifold and EGR clogged with soot	24,000–68,500 mi (middle half of 16 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA	Long past the range
6	Glow plugs and glow plug control	No clear mileage pattern: only 7 owner complaints state a mileage COMPUTED FROM NHTSA DATA	Any mileage

Colors compare mileage with reported failures, not the car's condition. Red: past the range. Amber: inside or approaching. Green: below, or not listed for a recall.

2 · RECALLS AND BULLETINS

Recalls to check for this 2004 Volkswagen Jetta

Safety recall repairs are free at Volkswagen dealers. On a car over 15 years old, ask the dealer whether a newer recall is still repaired free. Nothing here can tell whether a recall is open or already done on this VIN; only the official VIN lookup or a dealer can.

Official VIN check (2 minutes)

1. Go to nhtsa.gov/recalls and enter 3VWSR69MX4M123456.
2. Note every recall shown as “Recall incomplete” and keep a screenshot.
3. Ask a Volkswagen dealer for a campaign printout; it also lists completed campaigns.

1.9 TDI (ALH / BEW / BRM) AND 2.0 TDI PD (BHW) RECALLS WE TRACK

04V-586 · High-pressure diesel pump fastener (fuel leak, fire risk)

NHTSA lists this model and year: check by VIN

Some 2004–2005 PD diesels have a high-pressure (tandem) fuel pump built with the wrong fastener, which can let diesel leak near hot engine parts. Dealers replace the pump free. OFFICIAL [2]

☐ VIN checked ☐ Open: booked with dealer ☐ Completed (printout kept)

07V-063 · Brake light switch

NHTSA lists this model and year: check by VIN

The brake light switch can fail if it was fitted wrongly, so the brake lights stop working or stay on. Dealers fit a new switch free. OFFICIAL [5]

☐ VIN checked ☐ Open: booked with dealer ☐ Completed (printout kept)

EVERY RECALL NHTSA LISTS FOR THE 2004 VOLKSWAGEN JETTA (2)

RECALL	COMPONENT	WHAT CAN HAPPEN (NHTSA, SHORTENED)
07V-063 1.9 TDI (ALH / BEW / BRM) and 2.0 TDI PD (BHW) tracked	Brake lights · brake light switch	The brake lights can stop working or stay on, so drivers behind may get no warning when the car brakes. Details
04V-586 1.9 TDI (ALH / BEW / BRM) and 2.0 TDI PD (BHW) tracked	Diesel fuel system · high-pressure pump fastener	Diesel fuel can leak, and a leak near a source of ignition can start a fire. Details

Source: NHTSA recalls API, fetched 2026-10-28 and combined across NHTSA model names: JETTA. Safety categories (air bags, fire, brakes, stalling, roll-away and loss of control) are listed first; listings whose NHTSA text names another engine, or an aftermarket part, go last. OFFICIAL

Left out of this list (JETTA): 20E-064 (Beck/Arnley aftermarket master cylinder), 14E-007 (Gates aftermarket water pump) and 07E-023 (Cardone aftermarket master cylinders) cover aftermarket replacement parts only and are left out of this sample; they apply only if those parts were fitted.

SERVICE ACTIONS, BULLETINS AND WARRANTY PROGRAMS

Manufacturer bulletins and warranty programs for this engine are cited on each weak point in section 4, where they apply.

4 · THE 6 WEAK POINTS

Each weak point, one card each


Every figure carries its source. Retailer part numbers are shown only when the retailer lists them for this chassis (Mk4).

1 Timing belt, tensioner and water pump

Past the range

Severity: High: overheating, stalls, limp mode or a big bill · 11 mentions in counted NHTSA complaints COMPUTED FROM NHTSA DATA

At 165,000 mi this car is past the reported range (80,000 mi on the 2004–2006 BEW, BRM and BHW (VW figure as quoted by TDI parts specialists and VW customer care); 100,000 mi on the ALH once the 2003-updated belt and roller are fitted (earlier ALH parts: 40,000–80,000 mi). Overdue if there is no record). If the original parts are still fitted, have them checked and plan for them. Range: 80,000 mi on the 2004–2006 BEW, BRM and BHW (VW figure as quoted by TDI parts specialists and VW customer care); 100,000 mi on the ALH once the 2003-updated belt and roller are fitted (earlier ALH parts: 40,000–80,000 mi). Overdue if there is no record SHOP/RETAILER [6][7][8]



WHAT FAILS OFFICIAL [1]

The camshaft and injection pump are driven by a toothed rubber belt. This is an interference engine: if the belt or its tensioner fails, the valves hit the pistons. Belt jobs are usually done with the tensioner, idlers and water pump.

SYMPTOMS

- Usually no warning before it breaks
- Squeal or rattle from the belt cover on worn idlers
- Coolant seep at the water pump

IF IT'S LEFT TOO LONG

A broken belt stops the engine at once and usually bends valves, so the head has to come off.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Replace on schedule. On a car with no belt record, treat it as due before anything else.

ESTIMATED REPAIR COST

Timing belt replacement, 2003–2004 Jetta (RepairPal model-year rows; 2006 Jetta $1,386–$1,750; not split by engine, no water pump or rollers)	**Our price is in the plan above** ask us for a written quote
Engine damage after a belt failure: no published price	**No published price** reported range for the bill after a failure

Where the numbers come from: RepairPal lists the timing belt job by model year, not by engine: 2003–2004 Jetta $1,330–$1,828 and 2006 Jetta $1,386–$1,750 [3]. Its 2000–2002 rows ($687–$967) look like the gas 2.0 and are not used for the TDI. The estimate leaves out the water pump, tensioner and pulleys; TDI belt jobs that include the pump and injection-pump or cam timing often cost more. Interval: the ALH figure depends on which belt and roller are fitted, so a car with an older belt of unknown part number should be treated as due at the shorter figure [6].

PARTS FOR MK4

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- When was the timing belt last replaced, at what mileage? Invoice?
- Was the water pump and tensioner done with it?

2 Clutch and dual-mass flywheel (manual cars)

Long past the range

Severity: High: overheating, stalls, limp mode or a big bill · 86 mentions in counted NHTSA complaints COMPUTED FROM NHTSA DATA

At 165,000 mi this car is long past the reported range (20,200–76,500 mi (middle half of 50 owner complaints that state a mileage)). Many cars at this mileage have already had this repaired, and some never had the fault. Check the records and the part itself before planning it. Range: 20,200–76,500 mi (middle half of 50 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA [1]



WHAT FAILS OFFICIAL [1]

The TDI's high low-speed torque is hard on the clutch, and the dual-mass flywheel behind it can wear out or break up. Owners report clutches slipping or failing, sometimes more than once, and flywheels coming apart. The Mk5 Jetta with the DSG gearbox has a dual-mass flywheel too.

SYMPTOMS

- Clutch slips under load (revs rise, speed does not)
- Rattle or clunk at idle that stops when the clutch is pressed
- Judder pulling away
- Pedal sticking or going to the floor

IF IT'S LEFT TOO LONG

A failed flywheel can break up and damage the gearbox housing or leave the car stranded.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Replace clutch and flywheel together when either one is worn out.

ESTIMATED REPAIR COST

No published price for the clutch alone	**Our price is in the plan above** ask us for a written quote
Owner-reported clutch and flywheel bills in NHTSA complaints (n=26)	**$1,685–$2,650** COMPUTED FROM NHTSA DATA [1] reported range for the bill after a failure

Where the numbers come from: Computed from 26 NHTSA owner complaints that quote a clutch or flywheel bill (middle half; median $2,000). Examples: ODI 10068281, 10100790, 10261007, 10150659. Owner-reported, often dealer prices.

PARTS FOR MK4

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US


- Has the clutch or flywheel been replaced? With a single-mass conversion?
- Any slipping or rattle at idle?

3 Camshaft lobe and lifter wear (2004–2006 PD engines)

Past the range

Severity: High: overheating, stalls, limp mode or a big bill · 20 mentions in counted NHTSA complaints COMPUTED FROM NHTSA DATA

At 165,000 mi this car is past the reported range (70,100–100,000 mi (middle half of 12 owner complaints that state a mileage)). If the original parts are still fitted, have them checked and plan for them. Range: 70,100–100,000 mi (middle half of 12 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA [1]



Applies to: 2004–2006 BEW and BRM engines and the 2004–2005 Passat BHW

WHAT FAILS FORUM/BLOG [4][1]

On the Pumpe Düse engines (BEW, BRM and the Passat's BHW) the camshaft also drives the unit injectors, which puts extra load on the lobes and roller rockers. Lobes and lifters can wear down, especially with oil that does not meet Volkswagen's 505.01 specification. Owners describe misfires, smoke, loss of power and ticking.

SYMPTOMS

- Ticking or tapping from the top of the engine
- Misfire or rough running with no code
- Loss of power and black or white smoke
- Hard starting

IF IT'S LEFT TOO LONG

Worn lobes spread metal through the oil and can take out the lifters and injectors; the repair grows the longer it waits.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Use oil that meets VW 505.01 and change it on time; check the cam through the oil filler or valve cover when buying a high-mileage car.

ESTIMATED REPAIR COST

Valve-cover inspection of the cam lobes (about 1 hour)	**Our price is in the plan above** ask us for a written quote
Owner-reported camshaft and lifter repair bills in NHTSA complaints (n=9)	**$2,900–$4,500** COMPUTED FROM NHTSA DATA [1] reported range for the bill after a failure

Where the numbers come from: Computed from 9 NHTSA owner complaints that quote a camshaft/lifter bill (middle half; median $3,000). Examples: ODI 10253809, 10549538, 10424367, 10453610. Inspection ESTIMATE: about one hour of labor at $100–160 per hour (our assumption; no published labor time).

PARTS FOR MK4

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US


- What oil has been used (VW 505.01)? Oil-change records?
- Has the camshaft or lifters been replaced?

4 Turbo vanes, boost control and MAF (loss of power)

Long past the range

Severity: Medium: leaks and wear · 48 mentions in counted NHTSA complaints COMPUTED FROM NHTSA DATA

At 165,000 mi this car is long past the reported range (42,000–81,000 mi (middle half of 21 owner complaints that state a mileage)). Many cars at this mileage have already had this repaired, and some never had the fault. Check the records and the part itself before planning it. Range: 42,000–81,000 mi (middle half of 21 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA [1]



WHAT FAILS OFFICIAL [1]

The variable-vane turbo can stick from soot, and the boost control valve (N75), vacuum lines or mass airflow sensor can fail. The car then goes into limp mode with little power, often on hills or when merging.

SYMPTOMS

- Sudden loss of power under load
- Check-engine light with boost codes
- Black smoke
- Car recovers after a restart

IF IT'S LEFT TOO LONG

Not usually damaging by itself, but a seized turbo or a neglected boost leak leads to a turbo replacement.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Diagnose boost codes early; check vacuum lines, N75 valve and MAF before replacing the turbo.

ESTIMATED REPAIR COST

No published price for the diagnosis or valve	**Our price is in the plan above** ask us for a written quote
Owner-reported turbo and boost-system bills in NHTSA complaints (n=15)	**$1,440–$3,500** COMPUTED FROM NHTSA DATA [1] reported range for the bill after a failure

Where the numbers come from: Computed from 15 NHTSA owner complaints that quote a bill for turbo or boost-control repairs (middle half; median about $2,400). Examples: ODI 10068281, 10066579, 10071335, 10023892. The bills mix full turbo replacement with smaller repairs.

PARTS FOR MK4

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- Any limp mode or loss of power on hills?
- Turbo or MAF replaced?

---

5 Intake manifold and EGR clogged with soot

Long past the range

Severity: Medium: leaks and wear · 20 mentions in counted NHTSA complaints

COMPUTED FROM NHTSA DATA

At 165,000 mi this car is long past the reported range (24,000–68,500 mi (middle half of 16 owner complaints that state a mileage)). Many cars at this mileage have already had this repaired, and some never had the fault. Check the records and the part itself before planning it. Range: 24,000–68,500 mi (middle half of 16 owner complaints that state a mileage) COMPUTED FROM NHTSA DATA [1]



Most reports are on 2000–2003 ALH engines

WHAT FAILS OFFICIAL [1]

Oil vapour from the crankcase breather mixes with soot from the EGR valve and builds a tar-like layer in the intake manifold. On the ALH engine it can choke the intake enough to cut power and mimic a turbo failure.

ESTIMATED REPAIR COST

Intake and EGR cleaning: no published price	**Our price is in the plan above** ask us for a written quote

SYMPTOMS

- Gradual loss of power
- Black smoke under load
- Check-engine light, sometimes with EGR or boost codes

IF IT'S LEFT TOO LONG

Power keeps falling; dealers have replaced turbos when the intake was the real cause.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Clean the intake manifold and EGR passages when power falls off, before replacing the turbo.

No published price	**No published price** reported range for the bill after a failure

Where the numbers come from: Owner bills in NHTSA complaints that mention the EGR or intake range widely (middle half $390–$5,400, n=12) because many also include turbo or injector work, so we do not show them as a price.

PARTS FOR MK4

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- Has the intake manifold been cleaned? When?

---

6 Glow plugs and glow plug control

Any mileage

Severity: Medium: leaks and wear · 19 mentions in counted NHTSA complaints

COMPUTED FROM NHTSA DATA

Reports cover a wide mileage span (No clear mileage pattern: only 7 owner complaints state a mileage), so mileage doesn't say much here. Range: No clear mileage pattern: only 7 owner complaints state a mileage COMPUTED FROM NHTSA DATA [1]

WHAT FAILS OFFICIAL [1]

Glow plugs heat the combustion chambers for cold starts. Failed plugs, their wiring or the control relay/module make the engine hard to start in cold weather and can set a glow plug light.

SYMPTOMS

- Long cranking when cold
- Rough running and white smoke for the first minute
- Flashing glow plug light

IF IT'S LEFT TOO LONG

Cold-weather no-starts; a plug left in place too long can break off in the head when removed.

IS IT WORTH DOING EARLY? OUR ESTIMATE

Test and replace failed plugs before winter.

ESTIMATED REPAIR COST

No published price	**Our price is in the plan above** ask us for a written quote
Owner-reported glow plug repair bills in NHTSA complaints (n=7)	**$800–$1,225** COMPUTED FROM NHTSA DATA [1] reported range for the bill after a failure

Where the numbers come from: Computed from 7 NHTSA owner complaints that quote a glow plug bill (middle half). Small sample, and some bills include the control module or wiring.

PARTS FOR MK4

- Ask your parts supplier for the OE part number for this VIN.

QUESTIONS TO ASK US

- Any hard starting in cold weather?
- Glow plugs replaced? When?

5 · ALSO REPORTED, NOT RANKED

Other themes in 1.9 TDI (ALH / BEW / BRM) and 2.0 TDI PD (BHW) owner complaints

Every NHTSA complaint theme with 10 or more counted reports is either a weak point above or explained here.

THEME	COMPLAINTS	WHY IT ISN'T A WEAK POINT
Brakes	50	Mostly rear brake wear and brake-light switch complaints (recall 07V-063); not engine faults.
Fuel leak / fuel pumps	32	Recall 04V-586 replaced high-pressure (tandem) pumps with a bad fastener on 2004–2005 PD cars; in-tank lift pump failures also stall later cars. Check the recall is done.
Automatic transmission	17	The four-speed (01M) automatic in Mk4 cars and the six-speed in the Mk5 Jetta; transmission faults, not engine faults.

How this report is built

Inputs. VIN, model year, model, mileage and build month (if entered). Model and engine are checked with NHTSA's vPIC decoder.

Mileage positions. Below: more than 10,000 miles before the reported range. Approaching: within 10,000. Inside: in the range, or past the start of an open-ended range. Past: beyond the top of the range. These bands are our rules, not an industry standard.

The plan. Critical items inside or past their range go first; high-severity items follow, and jobs that share labor are bundled. At most three jobs land in “Recommended now”. Leaks that are cheap to watch are fixed on condition; inspections are asked for at each service.

Costs. Published independent-shop ranges from shop quotes, retailer prices and owner reports. Shop prices come from the issuing shop. The worst-case cost of every item failing is not shown: it isn't an expected cost.

Labels. `OFFICIAL` NHTSA/Volkswagen documents · `SHOP/RETAILER` parts prices and shop articles · `FORUM/BLOG` owner forums and blogs · `COMPUTED FROM NHTSA DATA` our analysis of NHTSA data · `OUR ESTIMATE` ours.

NHTSA complaint data. Pulled Oct 28, 2026 from NHTSA's complaints API for 2000–2006 Jetta, Golf and New Beetle complaints that name the TDI, diesel or 1.9L, and 2004–2005 Passat complaints that name the TDI or diesel. Complaints that do not name the engine are missed, so the counts under-count: 458 complaints. Some of these nameplates were sold with other engines too; for those we kept only complaints whose text names this engine, which under-counts. Themes are keyword matches on the complaint text. `COMPUTED FROM NHTSA DATA`

THEME	COMPLAINTS	IN THIS REPORT
Clutch / dual-mass flywheel	86	Item 2
Brakes	50	Also reported
Turbo / loss of boost	48	Item 4
Fuel leak / fuel pumps	32	Also reported
EGR / intake clogging	20	Item 5
Camshaft / lifters	20	Item 3
Glow plugs	19	Item 6
Automatic transmission	17	Also reported
Timing belt	11	Item 1

Limits: complaints are self-reported and not adjusted for cars sold; keyword matching over- and under-counts; owners rarely file safety complaints about oil seeps, so leaks look rarer than they are.

SOURCES

1. NHTSA owner complaints for 2000–2006 Jetta, Golf and New Beetle TDI and 2004–2005 Passat TDI, pulled Oct 28, 2026 (ODI numbers in the cost notes) `OFFICIAL`
https://www.nhtsa.gov/vehicle/2004/VOLKSWAGEN/JETTA/4%2520DR/FWD

2. NHTSA recall 04V-586: high-pressure diesel pump fastener, checked Oct 28, 2026 `OFFICIAL`
https://www.nhtsa.gov/recalls?nhtsaId=04V586000

3. RepairPal estimator: Volkswagen Jetta timing belt replacement, model-year rows (rows not split by engine), read Oct 28, 2026 `SHOP/RETAILER`
https://repairpal.com/estimator/volkswagen/jetta/timing-belt-replacement-cost

4. iATN technician forum: TDI camshaft wear warning signs (2004–2006 PD engines and 505.01 oil) `FORUM/BLOG`
https://iatn.net/forums/13/41481/tdi-camshaft-wear-warning-signs

5. NHTSA recall 07V-063: brake light switch, checked Oct 28, 2026 `OFFICIAL`
https://www.nhtsa.gov/recalls?nhtsaId=07V063000

6. KermaTDI (TDI parts specialist): ALH timing belt kit page with the VW belt-interval timeline for the ALH (1999.5: 40,000 mi automatic / 60,000 mi manual; 2002 belt update: 60,000 / 80,000 mi; 2003 roller update: 100,000 mi regardless of gearbox), read Oct 28, 2026 SHOP/RETAILER
https://kermatdi.com/i-1022-alh-deluxe-100000-mile-timing-belt-kit-complete-kit-vw-alh-tdi-19982003-kermatdi.html

7. KermaTDI (TDI parts specialist): BRM timing belt kit for the 2005.5–2006 Jetta TDI, "service interval for this belt: 80,000 miles", read Oct 28, 2026 SHOP/RETAILER
https://kermatdi.com/i-605-brm-timing-belt-kit.html

8. TDIClub forum: owner posts letters from VW customer care (Nov 2008) recommending timing-belt replacement at 80,000 miles (inspection every 40,000) on a 2005 Passat TDI FORUM/BLOG
https://forums.tdiclub.com/index.php?threads/mikestdi-letter-from-vw-timing-belt-interval.229870/

This report contains no affiliate links; retailer prices are quoted as price sources only. Found an error? Email hello@repairahead.com.

PLEASE READ

Important

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN.

Informational only. This report is not a mechanical inspection, a diagnosis, or professional, legal or financial advice. It was issued by Springfield Euro Auto using RepairAhead data; the inspection findings and prices are the shop's.

Reported ranges and estimates, not predictions

Failure mileages are reported ranges compiled from public owner complaints, manufacturer bulletins, recalls and repair-shop reports. Costs are estimates. Parts can fail earlier, later or not at all, and other problems can occur. Statistics from owner complaints describe past reports to NHTSA; NHTSA has not reviewed or endorsed this analysis.

Safety issues go to a dealer

If you notice overheating, a burning or fuel smell, smoke, a brake-assist problem, stalling or loss of power, pull over when it's safe and contact a Volkswagen dealer or qualified shop. Safety recall repairs are free at Volkswagen dealers. Confirm recalls for this VIN at nhtsa.gov/recalls.

No warranty

Provided “as is”, without warranties of any kind, under the Terms of Use at repairahead.com/terms.

Trademarks and independence

Not affiliated with Volkswagen AG or Volkswagen Group of America. Volkswagen and model names are trademarks of Volkswagen AG, used only to identify vehicles.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN.