SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

TECHNICIAN WORKSHEET · 2.7L / 3.0L ECOBOOST V6
RA-FDEB27-123456-20261028

# 2017 Ford F-150 · F-150 XLT SuperCrew 2.7 EcoBoost 4x4 · 4WD

1FTEW1EP1HF123456

| ODOMETER IN | DOOR-JAMB BUILD (MM/YY) | RO # | TECHNICIAN / DATE |
|---|---|---|---|
| 95,000 | | | |

## A · RECALLS AND CAMPAIGNS TO VERIFY (DEALER PRINTOUT OR NHTSA.GOV)

| | |
|---|---|
| **26V-237** · Transmission · range sensor signal | ☐ Open ☐ Done ☐ N/A |
| **25V-236** · Brakes · master cylinder leak | ☐ Open ☐ Done ☐ N/A |
| **19V-278** · Engine block heater · cable splice (repeat of 18V-894) | ☐ Open ☐ Done ☐ N/A |
| **18V-894** · Engine block heater · cable splice | ☐ Open ☐ Done ☐ N/A |
| **18V-568** · Seat belts · front pretensioner | ☐ Open ☐ Done ☐ N/A |
| **17V-652** · Doors · latch (cable or frozen latch) | ☐ Open ☐ Done ☐ N/A |
| **17V-599** · Seats · passenger seat belt anchor weld | ☐ Open ☐ Done ☐ N/A |
| **17V-529** · Air bags · passenger frontal inflator | ☐ Open ☐ Done ☐ N/A |
| **17V-526** · Seat belts · left rear inflatable buckle | ☐ Open ☐ Done ☐ N/A |
| **17V-332** · Seats · driver seat back recliner welds | ☐ Open ☐ Done ☐ N/A |

## B · INSPECTION POINTS, IN PLAN ORDER

**1. Oil pan leak (RTV seal), 2015–2017** — Watch · Any mileage (2015–2017 F-150 2.7L; 2015–2017 Edge, 2016–2017 MKX, 2017 Fusion/MKZ/Continental)

Inspect the pan seam for wet oil ☐ OK ☐ Watch ☐ Fix

Pan: dry / seep / wet

Parts (P552): Ask your parts supplier for the OE part number for this VIN.

## FACTORY MAINTENANCE DUE BY 125,000 MI (ASK FOR RECORDS)

| | |
|---|---|
| **Spark plugs** · every 100,000 mi · at 100,000 mi · $249 | ☐ Done (records) ☐ Due ☐ Quoted |
| **Engine coolant** · first at 100,000 mi, then every 50,000 mi or 3 years · due by age: every 3 years (check records) · From $179 | ☐ Done (records) ☐ Due ☐ Quoted |

## C · ALSO REPORTED FOR THE 2.7L / 3.0L ECOBOOST V6, QUICK CHECKS

- **Transmission** (74 complaints): Counts every transmission complaint (10-speed automatic); not an engine fault.
- **Turbo / loss of power** (39 complaints): Mixed causes; several recalls (24V-635 valves, 25V-455 low-pressure fuel pump) cause loss of power.

## NOTES FOR THE ADVISOR

Record findings here (OK / Watch / Fix and measurements); the advisor adjusts the quote before the handout is printed or sent.



Reference only. Follow Ford repair procedures and your shop's judgment.