SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

YOUR CAR AT A GLANCE
OCTOBER 28, 2026

2015 Honda Fit · 118,000 mi

1.5 L15 · VIN 3HGGK5H52FM123456

Now: inspection (misfire from carbon on the intake valves (2015–2017 and 2020 Fit); fuel injectors wear and leak (2015–2016)), recall check (plug-top ignition coils (2015 recall)).
Plan: nothing else on the list before 148,000 mi; plus 1 factory maintenance item below.
Recalls: 4 safety recalls listed for this model year; we check the VIN.

Recommended now today or at the next visit — $140

Inspection: check now, while it's cheaper to fix — $140

inspection EXAMPLE
☐ Approve

Misfire from carbon on the intake valves (2015–2017 and 2020 Fit): Past the range (40,000–80,000 mi, the middle half of 54 owner reports) · if it fails: $180–$290
Fuel injectors wear and leak (2015–2016): Long past the range (44,000–53,000 mi, the middle half of 15 owner reports) · if it fails: $1,650–$2,230
The ones long past their range may already be fixed: we check the records first.
Known weak points for this engine, not findings on your car. The inspection shows whether yours has early signs.

Plug-top ignition coils (2015 recall) — Free if open

Recall 15V-559 is listed for this model year. Check the VIN; the repair is free at a Honda dealer if it is open.

Factory maintenance due by 148,000 mi, if not already done — $129

Brake fluid — $129

every 3 years · if the records don't show it done
☐ Approve

We'll keep an eye on at each visit

VTC actuator rattle at cold start (2015–2016) (inspect at each service; fix at the first sign) · Catalytic converter (P0420) (inspect at each service; fix at the first sign)

Recommended now
$140
Springfield Auto Care prices (example)

Planned through 148,000 mi
$269
Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don't show it done. Excludes "watch" and optional items.

Safety recalls NHTSA lists for this model year (4)

15V-574 CVT software (drive pulley shaft) · **15V-559** Plug-top ignition coils · **15V-697** Rear grab handle brackets (LX without sunroof) · **14V-563** Side curtain air bag · A-pillar trim

A model-year list, not a VIN check. Repairs are free at a Honda dealer if open. Check this VIN at nhtsa.gov/recalls.

Recalls: Springfield Auto Care checks this VIN for open recalls, including 15V-559, 15V-574. Open recalls are repaired free at a Honda dealer.

Questions? Ask Springfield Auto Care at service@springfield-auto-care.example. The full report, with sources for every figure, is one scan away.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN. "If it fails" figures are repair bills reported in public sources or, where none are published, our estimates (each one labeled in the full report); they are not predictions. Open recalls are free at a Honda dealer. Prices are estimates before tax, shop supplies and disposal fees, and may change after inspection. Not a written repair estimate: we confirm the price with you before any work. Data: RepairAhead, 2026-10-28.r1. Not affiliated with Honda Motor Co., Ltd.