SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

2010 Acura RDX · TB1 RDX SH-AWD (2.3L turbo) · AWD

5J8TB1H56AA123456

ODOMETER IN: 110,000 | DOOR-JAMB BUILD (MM/YY): | RO #: | TECHNICIAN / DATE:

A · RECALLS AND CAMPAIGNS TO VERIFY (DEALER PRINTOUT OR NHTSA.GOV)

19V-182 · Air bags · driver frontal (replacement inflator) ☐ Open ☐ Done ☐ N/A

16V-061 · Air bags · driver frontal ☐ Open ☐ Done ☐ N/A

B · INSPECTION POINTS, IN PLAN ORDER

1. Turbo wastegate / flow actuator failure (boost faults)

Watch · Any mileage (Owners report it at higher mileage; no maker bulletin gives a range)

Scan for P0234 / P2263 / P0299 ☐ OK ☐ Watch ☐ Fix

Check wastegate and flow actuator linkage for wear ☐ OK ☐ Watch ☐ Fix

Check boost control solenoid and vacuum lines ☐ OK ☐ Watch ☐ Fix

Boost: normal / low / over

Scan for: P0234, P2263, P0299

Parts (TB1): Ask your parts supplier for the OE part number for this VIN.

2. Catalyst code P0420 from a lean fuel-tank condition

Watch · Any mileage (2007–2010 RDX built before the bulletin VIN breaks)

Scan for P0420 and lean codes ☐ OK ☐ Watch ☐ Fix

Check the VIN against the bulletin range ☐ OK ☐ Watch ☐ Fix

Scan for: P0420

Parts (TB1): Ask your parts supplier for the OE part number for this VIN.

3. Oil leak at the cylinder head cover (valve cover)

Watch · Any mileage (2007–2010 RDX)

Inspect the valve cover edge for wet oil ☐ OK ☐ Watch ☐ Fix

Cover: dry / seep / wet

Parts (TB1): Ask your parts supplier for the OE part number for this VIN.

FACTORY MAINTENANCE DUE BY 140,000 MI (ASK FOR RECORDS)

Brake fluid · every 3 years · $129 ☐ Done (records) ☐ Due ☐ Quoted

C · ALSO REPORTED FOR THE 2.3L K23A1 TURBO, QUICK CHECKS

- **Air bags** (82 complaints): Takata driver air bag inflator recalls; not an engine fault. Check the VIN.

NOTES FOR THE ADVISOR

Record findings here (OK / Watch / Fix and measurements); the advisor adjusts the quote before the handout is printed or sent.

Reference only. Follow Acura repair procedures and your shop's judgment.