SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

YOUR CAR AT A GLANCE
OCTOBER 27, 2026

2015 Jeep Cherokee · 98,000 mi

2.4 Tigershark · VIN 1C4PJLCB9FW123456

Now: inspection (oil consumption (low oil, stalling); nine-speed automatic transmission (948TE)).
Plan: nothing else on the list before 128,000 mi; plus 2 factory maintenance items below.
Recalls: 7 safety recalls listed for this model year; we check the VIN.

Recommended now today or at the next visit — $140

Inspection: check now, while it's cheaper to fix — $140

inspection EXAMPLE
☐ Approve

Oil consumption (low oil, stalling): Long past the range (5,000–35,000 mi, the middle half of 206 owner reports) · **may be free at a Jeep dealer** (free PCM update under W20 / W84) · if it fails outside that coverage: $760–$1,950 labor only, parts extra
Nine-speed automatic transmission (948TE): Past the range (10,000–54,000 mi, the middle half of 311 owner reports) · if it fails: $830–$5,500
The ones long past their range may already be fixed: we check the records first.
Known weak points for this engine, not findings on your car. The inspection shows whether yours has early signs.

Factory maintenance due by 128,000 mi, if not already done — From $428

Spark plugs — $249

at 100,000 mi · if the records don't show it done
☐ Approve

Engine coolant — From $179

due by age: 10-year limit passed (check records) · if the records don't show it done
☐ Approve

We'll keep an eye on at each visit

Ignition coil boot misfire (inspect at each service; fix at the first sign)

Recommended now
$140
Springfield Auto Care prices (example)

Planned through 128,000 mi
From $568
Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don't show it done. Excludes "watch" and optional items.

Safety recalls NHTSA lists for this model year (7 of 9)

23V-338 Power liftgate · control module short · **18V-332** Cruise control · cannot be switched off · **16V-529** Transmission · 9-speed sensor wiring · **15V-826** Power liftgate · control module water leak · **15V-676** A/C hose · touches exhaust manifold · **15V-393** Power liftgate · control module water leak · **15V-041** Air bags · unintended side air bag deployment

A model-year list, not a VIN check. The full report lists the others. Repairs are free at a Jeep dealer if open. Check this VIN at nhtsa.gov/recalls.

Recalls: Springfield Auto Care checks this VIN for open recalls. Open recalls are repaired free at a Jeep dealer.

Questions? Ask Springfield Auto Care at service@springfield-auto-care.example. The full report, with sources for every figure, is one scan away.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN. "If it fails" figures are repair bills reported in public sources or, where none are published, our estimates (each one labeled in the full report); they are not predictions. Open recalls are free at a Jeep dealer. Prices are estimates before tax, shop supplies and disposal fees, and may change after inspection. Not a written repair estimate: we confirm the price with you before any work. Data: RepairAhead, 2026-11-10.r1. Not affiliated with FCA US LLC (Stellantis).