SAC

Springfield Auto Care EXAMPLE SHOP
service@springfield-auto-care.example

YOUR CAR AT A GLANCE
OCTOBER 28, 2026

2003 Ford F-150 · 125,000 mi

4.6/5.4 2V · VIN 1FTRW08L63K123456

Now: inspection (spark plug blow-out (stripped plug threads)), recall check (speed control deactivation switch can overheat (fire risk)).
Plan: nothing else on the list before 155,000 mi; plus 2 factory maintenance items below.
Recalls: 4 safety recalls listed for this model year; we check the VIN.

Recommended now today or at the next visit — $140

Inspection: check now, while it's cheaper to fix — $140

inspection EXAMPLE

Spark plug blow-out (stripped plug threads): Past the range (51,000–101,000 mi, the middle half of 132 owner reports) · if it fails: $660–$3,480

☐ Approve

Known weak point for this engine, not a finding on your car. The inspection shows whether yours has early signs.

Speed control deactivation switch can overheat (fire risk) — Free if open

Recalls 07V-078, 07V-336 are listed for this model year. Check the VIN; the repair is free at a Ford dealer if it is open.

Factory maintenance due by 155,000 mi, if not already done — $508

Spark plugs — $249

were due at 100,000 mi (check records) · if the records don't show it done

☐ Approve

Automatic transmission fluid — $259

at 150,000 mi · if the records don't show it done

☐ Approve

We'll keep an eye on at each visit

Broken exhaust manifold studs (tick) (inspect at each service; fix at the first sign) · Ignition coil misfire (inspect at each service; fix at the first sign)

Recommended now
$140
Springfield Auto Care prices (example)

Planned through 155,000 mi
$648
Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don't show it done. Excludes "watch" and optional items.

Safety recalls NHTSA lists for this model year (4)

07V-336 Speed control · deactivation switch · **07V-078** Speed control · deactivation switch · **11V-385** Fuel tank · strap corrosion (salt-belt states) · **03V-349** Steering · pitman arm nut

A model-year list, not a VIN check. Repairs are free at a Ford dealer if open. On a car over 15 years old, ask the dealer whether a newer recall is still repaired free. Check this VIN at nhtsa.gov/recalls.

Recalls: Springfield Auto Care checks this VIN for open recalls, including 07V-078, 07V-336. Open recalls are repaired free at a Ford dealer.

Questions? Ask Springfield Auto Care at service@springfield-auto-care.example. The full report, with sources for every figure, is one scan away.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN. "If it fails" figures are repair bills reported in public sources or, where none are published, our estimates (each one labeled in the full report); they are not predictions. Open recalls are free at a Ford dealer (over 15 years old: ask the dealer). Prices are estimates before tax, shop supplies and disposal fees, and may change after inspection. Not a written repair estimate: we confirm the price with you before any work. Data: RepairAhead, 2026-10-28.r2. Not affiliated with Ford Motor Company.