SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

YOUR CAR AT A GLANCE
OCTOBER 28, 2026

# 2021 GMC Yukon Denali · 62,000 mi

6.2 V8 · VIN 1GKS2DKLXMR123456

**Now:** inspection (collapsed or broken valve lifters (misfire, tick)), recall check (connecting rod and crankshaft defects (L87, 2021–2024)).
**Plan:** nothing else on the list before 92,000 mi; plus 1 factory maintenance item below.
**Recalls:** 10 safety recalls listed for this model year; we check the VIN.

## Recommended now today or at the next visit — $140

### Inspection: check now, while it's cheaper to fix — $140

inspection EXAMPLE

**Collapsed or broken valve lifters (misfire, tick)**: Inside the range (16,000–84,000 mi, the middle half of 227 owner reports) · if it fails: $7,340–$13,000

Known weak point for this engine, not a finding on your car. The inspection shows whether yours has early signs.

☐ Approve

### Connecting rod and crankshaft defects (L87, 2021–2024) — Free if open

Recall 25V-274 is listed for this model year. Check the VIN; the repair is free at a GMC dealer if it is open.

## Factory maintenance due by 92,000 mi, if not already done — From $179

### Engine coolant — From $179

due by age: 5-year limit passed (check records) · if the records don't show it done

☐ Approve

Recommended now
**$140**
Springfield Auto Care prices (example)

Planned through 92,000 mi
**From $319**
Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don’t show it done. Excludes “watch” and optional items.

**Safety recalls NHTSA lists for this model year (10 of 12)**

**25V-274** Engine · 6.2L connecting rods and crankshaft · **22V-617** Seat belts · third-row buckle rivet · **22V-036** Driveline · rear driveshaft heat treatment · **21V-739** Fuel system · fuel pump control module · **21V-579** Brakes · electric brake booster calibration · **21V-455** Steering · power steering software · **21V-421** Air bags · warning light · **21V-190** Seat belts · third-row belts misrouted · **21V-064** Fuel system · fuel tank layers · **20V-811** Seat belts · incorrect anchor bolts

A model-year list, not a VIN check. The full report lists the others. Repairs are free at a GMC dealer if open. Check this VIN at nhtsa.gov/recalls.

**Recalls:** Springfield Auto Care checks this VIN for open recalls, including 25V-274. Open recalls are repaired free at a GMC dealer.

**Questions?** Ask Springfield Auto Care at service@springfield-auto-care.example. The full report, with sources for every figure, is one scan away.

**Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN.** “If it fails” figures are repair bills reported in public sources or, where none are published, our estimates (each one labeled in the full report); they are not predictions. Open recalls are free at a GMC dealer. Prices are estimates before tax, shop supplies and disposal fees, and may change after inspection. Not a written repair estimate: we confirm the price with you before any work. Data: RepairAhead, 2026-11-10.r1. Not affiliated with General Motors.