SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

YOUR CAR AT A GLANCE
OCTOBER 27, 2026

2016 Acura MDX · 90,000 mi

3.5 V6 · VIN 5FRYD4H49GB123456

Now: Timing belt, tensioner and water pump (interference engine), inspection (torque converter lock-up judder (automatic)), recall check (connecting rod bearing wear and seizure (recall 23V-751)).
Plan: nothing else on the list before 120,000 mi; plus 1 factory maintenance item below.
Recalls: 5 safety recalls listed for this model year; we check the VIN.

Recommended now today or at the next visit

Timing belt, tensioner and water pump (interference engine)

Ask us for a quote

Inside the range (Parts seller: replace at 90,000 mi (severe use) to 110,000 mi (normal use)) · if the records don't show it done

☐ Approve

Inspection: check now, while it's cheaper to fix

$140

Torque converter lock-up judder (automatic): Inside the range (55,000–107,000 mi, the middle half of 269 owner reports) · if it fails: $1,880–$5,000

inspection EXAMPLE

Known weak point for this engine, not a finding on your car. The inspection shows whether yours has early signs.

☐ Approve

Connecting rod bearing wear and seizure (recall 23V-751)

Free if open

Recall 23V-751 is listed for this model year. Check the VIN; the repair is free at an Acura dealer if it is open.

Factory maintenance due by 120,000 mi, if not already done — $129

Brake fluid

$129

every 3 years · if the records don't show it done

☐ Approve

We'll keep an eye on at each visit

Engine mounts (cracked or worn) (inspect at each service; fix at the first sign) · Transmission fluid warmer leaks coolant into the ATF (2016–2017 MDX, 9-speed) (ask for this check at every service)

Recommended now

$140 + 1 to quote

Springfield Auto Care prices (example)

Planned through 120,000 mi

$269 + 1 to quote

Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don't show it done. Excludes "watch" and optional items.

Safety recalls NHTSA lists for this model year (5 of 7)

23V-751 Engine · connecting rod bearings · **19V-060** Fuel system · fuel pump (3.5L V6) · **26V-365** Rear subframe · corrosion (salt states) · **23V-858** Fuel system · fuel pump · **16V-417** Fuel tank · welds

A model-year list, not a VIN check. The full report lists the others. Repairs are free at an Acura dealer if open. Check this VIN at nhtsa.gov/recalls.

Recalls: Springfield Auto Care checks this VIN for open recalls, including 23V-751, 19V-060. Open recalls are repaired free at an Acura dealer.

Questions? Ask Springfield Auto Care at service@springfield-auto-care.example. The full report, with sources for every figure, is one scan away.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN. "If it fails" figures are repair bills reported in public sources or, where none are published, our estimates (each one labeled in the full report); they are not predictions. Open recalls are free at an Acura dealer. Prices are estimates before tax, shop supplies and disposal fees, and may change after inspection. Not a written repair estimate: we confirm the price with you before any work. Data: RepairAhead, 2026-11-10.r1. Not affiliated with Honda Motor Co., Ltd.