SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

TECHNICIAN WORKSHEET · 2.0L EJ205 TURBO FLAT-FOUR
RA-EJ205-512345-20261028

2002 Subaru Impreza WRX · GD Impreza WRX 2.0 turbo sedan, 5-speed manual · AWD

JF1GD29692G512345

ODOMETER IN: 148,000 | DOOR-JAMB BUILD (MM/YY) | RO # | TECHNICIAN / DATE

A · RECALLS AND CAMPAIGNS TO VERIFY (DEALER PRINTOUT OR NHTSA.GOV)

09V-468 · Fuel delivery line can leak on cold starts (2002–2003 WRX, 16 cold-weather states) ☐ Open ☐ Done ☐ N/A

11V-464 · Suspension · front · control arm ☐ Open ☐ Done ☐ N/A

B · INSPECTION POINTS, IN PLAN ORDER

1. Fuel line and hose under the intake manifold leak on cold starts (recall 09V-468)

Check now · Any mileage (2002–2003 WRX (recall in 16 cold states; extended warranty elsewhere has expired); owners report 2004–2005 too)

- Check the VIN for 09V-468 ☐ OK ☐ Watch ☐ Fix
- Cold-start the engine and look under the intake manifold for wet fuel ☐ OK ☐ Watch ☐ Fix
- Check the fuel line clamps and hoses ☐ OK ☐ Watch ☐ Fix

Parts (GD): Ask your parts supplier for the OE part number for this VIN.

2. Clutch judder, sticking pedal and release bearing (manual cars)

Watch · Any mileage (2002–2005 WRX with manual transmission)

- Road test: pull away in first, cold and warm ☐ OK ☐ Watch ☐ Fix
- Check pedal return and feel ☐ OK ☐ Watch ☐ Fix
- Listen for release bearing noise with the pedal down ☐ OK ☐ Watch ☐ Fix
- Clutch engagement point: ___

Parts (GD): Ask your parts supplier for the OE part number for this VIN.

3. 5-speed manual gearbox: grinding into first, bearing wear and whine

Watch · Any mileage (2002–2005 WRX with 5MT)

- Road test every gear up and down, cold and warm ☐ OK ☐ Watch ☐ Fix
- Check gear oil level and look for metal on the drain plug ☐ OK ☐ Watch ☐ Fix

Parts (GD): Ask your parts supplier for the OE part number for this VIN.

4. Oil seepage at the oil filler tube O-ring

Watch · Any mileage (2002–2014 WRX with EJ engines)

- Inspect the filler tube base and rocker cover for oil ☐ OK ☐ Watch ☐ Fix

Parts (GD): Ask your parts supplier for the OE part number for this VIN.

FACTORY MAINTENANCE

Not on this report for this car. Check the service records and the maker's schedule (brake fluid, spark plugs, coolant, transmission fluid). ☐ Records checked ☐ Due ☐ Quoted

C · ALSO REPORTED FOR THE 2.0L EJ205 TURBO FLAT-FOUR, QUICK CHECKS

- **Brakes / ABS** (131 complaints): Many 2002–2003 complaints of ABS engaging on bumpy roads and long stops; not an engine fault.
- **Turbo / engine failure** (35 complaints): A few turbo and engine-failure complaints with no bulletin or recall pattern; most turbo mentions are fuel leaking near the turbo, covered under the fuel line item.
- **Suspension rust** (16 complaints): Front lower control arm corrosion in salt-belt states (recall 11V-464); not an engine fault.
- **Air bags** (15 complaints): Air bag complaints; not engine faults.

WHAT TO SAY AT THE COUNTER (ADVISOR)

1. Fuel line and hose under the intake manifold leak on cold starts (recall 09V-468)

On the 2002–2003 WRX the steel fuel delivery line and its rubber hose under the intake manifold shrink at different rates in the cold, so fuel seeps out at the joint on cold starts. Owners report it at all mileages, so it is worth a look at every visit. Our price is $480, before tax and shop supplies.

Ask: have you noticed strong raw-fuel smell, worst on cold mornings, or wet fuel on top of the engine under the intake manifold?

Adjust after the inspection. The report is not a diagnosis or a guarantee, so say what the technician found, not what the report predicts.

NOTES FOR THE ADVISOR

Record findings here (OK / Watch / Fix and measurements); the advisor adjusts the quote before the handout is printed or sent.