SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

TECHNICIAN WORKSHEET · 1.8L 1ZZ-FE
RA-TOY1ZZ-123456-20261027

2006 Toyota Corolla · E130 Corolla LE 1.8 · FWD

1NXBR32E16Z123456

ODOMETER IN: 120,000 | DOOR-JAMB BUILD (MM/YY) | RO # | TECHNICIAN / DATE

A · RECALLS AND CAMPAIGNS TO VERIFY (DEALER PRINTOUT OR NHTSA.GOV)

10V-384 · Engine computer can crack and stall the engine (2005–2008 Corolla and Matrix, 2WD)	☐ Open ☐ Done ☐ N/A
19V-741 · Air bags · passenger frontal inflator	☐ Open ☐ Done ☐ N/A
19V-627 · Air bags · passenger frontal (replacement unit)	☐ Open ☐ Done ☐ N/A
15V-286 · Air bags · passenger frontal inflator	☐ Open ☐ Done ☐ N/A
15V-285 · Air bags · passenger frontal inflator	☐ Open ☐ Done ☐ N/A

B · INSPECTION POINTS, IN PLAN ORDER

1. Oil consumption (piston rings)

Check now · Past the range (48,000–97,000 mi, the middle half of 35 owner reports)

Oil-consumption test (mark and measure over 1,000 miles)	☐ OK ☐ Watch ☐ Fix
Check plugs for oil fouling	☐ OK ☐ Watch ☐ Fix

Oil use: under 1 qt / 1–2 qt / more per 1,000 mi

Scan for: P0420, P0300

Parts (E130): Ask your parts supplier for the OE part number for this VIN.

2. Lean / misfire codes in freezing weather

Watch · Any mileage (2003–2008 Corolla and Matrix)

Scan for P0171, P030x and P0133	☐ OK ☐ Watch ☐ Fix
Check fuel trims cold	☐ OK ☐ Watch ☐ Fix

Scan for: P0171, P0300, P0133

Parts (E130): Ask your parts supplier for the OE part number for this VIN.

3. EVAP small-leak code P0456 (engine software)

Watch · Any mileage (2005–2008 Corolla and Matrix)

Scan for P0456	☐ OK ☐ Watch ☐ Fix
Check the gas cap seal	☐ OK ☐ Watch ☐ Fix

Scan for: P0456

Parts (E130): Ask your parts supplier for the OE part number for this VIN.

FACTORY MAINTENANCE DUE BY 150,000 MI (ASK FOR RECORDS)

Spark plugs · every 120,000 mi · at 120,000 mi · $249	☐ Done (records) ☐ Due ☐ Quoted
Engine coolant · first at 100,000 mi, then every 50,000 mi or 5 years · was due at 100,000 mi and by age (check records) · From $179	☐ Done (records) ☐ Due ☐ Quoted

C · ALSO REPORTED FOR THE 1.8L 1ZZ-FE, QUICK CHECKS

- **Air bags** (3371 complaints): Air-bag inflator recalls dominate the complaint count; not an engine fault.
- **Stalling / engine computer** (716 complaints): Recalls 10V-384 (Corolla, Matrix) and 10V-387 (Vibe): the 2005–2008 two-wheel-drive ECM can crack and stall the engine; check the VIN.
- **Transmission** (594 complaints): Counts every transmission complaint; not an engine fault.

WHAT TO SAY AT THE COUNTER (ADVISOR)

1. Oil consumption (piston rings)
Early 1ZZ-FE engines are widely reported to burn oil. At 120,000 mi your car is past the usual range, so if the original part is still fitted it is worth checking.
Ask: have you noticed oil level low between changes, or blue smoke at start-up?

Adjust after the inspection. The report is not a diagnosis or a guarantee, so say what the technician found, not what the report predicts.

NOTES FOR THE ADVISOR

Record findings here (OK / Watch / Fix and measurements); the advisor adjusts the quote before the handout is printed or sent.

Reference only. Follow Toyota repair procedures and your shop's judgment.