SAC **Springfield Auto Care** EXAMPLE SHOP
service@springfield-auto-care.example

YOUR CAR AT A GLANCE
OCTOBER 27, 2026

2022 Toyota Tundra · 52,000 mi

3.4TT V35A · VIN 5TFLA5DB7NX123456

Now: recall check (main bearing failure from machining debris (recalled engines)).
Plan: nothing else on the list before 82,000 mi; plus 1 factory maintenance item below.
Recalls: 5 safety recalls listed for this model year; we check the VIN.
Warranty: may still be under Toyota's powertrain warranty (usually 5 years or 60,000 mi from the day it was first sold). A covered engine or transmission repair is free at a Toyota dealer, so we check the coverage before quoting one.

Recommended now today or at the next visit

Main bearing failure from machining debris (recalled engines)

Free if open

Recalls 24V-381, 25V-767 are listed for this model year. Check the VIN; the repair is free at a Toyota dealer if it is open.

Factory maintenance due by 82,000 mi, if not already done — $249

Spark plugs — $249

were due at 40,000 mi, next 80,000 mi · if the records don't show it done

☐ Approve

We'll keep an eye on at each visit

Random-misfire check-engine light (engine software update) (inspect at each service; fix at the first sign) · Hesitation pulling away from a rolling stop (transmission software) (inspect at each service; fix at the first sign) · Turbocharger wastegate actuator faults (inspect at each service; fix at the first sign) · Oil leak at the oil filter seal in freezing weather (inspect at each service; fix at the first sign)

Recommended now

Free recall check

Springfield Auto Care prices (example)

Planned through 82,000 mi

$249

Now + next 12 months + next 30,000 miles, with the factory maintenance on this report if the records don't show it done. Excludes "watch" and optional items.

Safety recalls NHTSA lists for this model year (5 of 9)

25V-767 Engine · main bearings (machining debris), expansion · **24V-381** Engine · main bearings (machining debris) · **23V-566** Fuel system · fuel tube near the brake lines · **22V-661** Brakes · electronic parking brake · **22V-445** Axle · rear axle shaft nuts

A model-year list, not a VIN check. The full report lists the others. Repairs are free at a Toyota dealer if open. Check this VIN at nhtsa.gov/recalls.

Recalls: Springfield Auto Care checks this VIN for open recalls, including 24V-381, 25V-767, 23V-566, 24V-125. Open recalls are repaired free at a Toyota dealer.

Questions? Ask Springfield Auto Care at service@springfield-auto-care.example. The full report, with sources for every figure, is one scan away.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN. "If it fails" figures are repair bills reported in public sources or, where none are published, our estimates (each one labeled in the full report); they are not predictions. Open recalls are free at a Toyota dealer. Prices are estimates before tax, shop supplies and disposal fees, and may change after inspection. Not a written repair estimate: we confirm the price with you before any work. Data: RepairAhead, 2026-10-27.r1. Not affiliated with Toyota Motor Corporation.