SEA **Springfield Euro Auto** EXAMPLE SHOP
service@springfield-euro-auto.example

YOUR CAR AT A GLANCE
OCTOBER 27, 2026

2020 Mercedes-Benz GLE450 · 55,000 mi

M256 · VIN 4JGFB5KB6LA123456

Now: inspection (48 V system: battery, DC/DC converter, starter-generator).
Plan: nothing else on the list before 85,000 mi.
Recalls: 17 safety recalls listed for this model year; we check the VIN.
Maintenance: the maker's schedule (brake fluid, spark plugs, coolant, transmission fluid) isn't on this report yet; ask us what's due for your car.

Recommended now today or at the next visit — $165

Inspection: check now, while it's cheaper to fix — $165

48 V system: battery, DC/DC converter, starter-generator: Past the range (5,000–24,000 mi, the middle half of 11 owner reports) · **may be free at a Mercedes-Benz dealer** (free software update under campaign 2025050001 if open)
inspection EXAMPLE
☐ Approve

Known weak point for this engine, not a finding on your car. The inspection shows whether yours has early signs.

We'll keep an eye on at each visit

Rear crankshaft seal leak (oil on the starter-generator) (inspect at each service; fix at the first sign) · Electric coolant pump faults (red coolant warning) (inspect at each service; fix at the first sign) · Oil pressure warning (sticking control valve) (inspect at each service; fix at the first sign) · Turbo charge-air check valve (P22C8 / P22C9) (inspect at each service; fix at the first sign)

Recommended now
$165
Springfield Euro Auto prices (example)

Planned through 85,000 mi
$165
Nothing else on the list before 85,000 mi. Now + next 12 months + next 30,000 miles. Excludes “watch” and optional items.

Safety recalls NHTSA lists for this model year (17 of 30)

24V-118 Transmission · downshift software · **21V-961** Fuel system · fuel rail and injectors · **19V-572** Fuel system · filler pipe weld · **24V-207** Electrical · 48 V ground connection · **23V-177** Air conditioning · drain hoses · **22V-231** Electrical · 48 V ground cable · **21V-818** Seats · assembly · **21V-288** Air conditioning · drain hoses · **21V-057** Dashboard · surface bonding · **20V-671** Seat belts · rear middle buckle · **20V-626** Electrical · grille star ground · **20V-329** Suspension · struts and shocks · **20V-226** Air bags · rear seat wiring · **20V-172** Body · rear crossmember welds · **19V-587** Air conditioning · drain hoses · **19V-540** Active Brake Assist · radar · **19V-458** Air bags · passenger frontal

A model-year list, not a VIN check. The full report lists the others. Repairs are free at a Mercedes-Benz dealer if open. Check this VIN at nhtsa.gov/recalls.

Recalls: Springfield Euro Auto checks this VIN for open recalls, including 19V-572, 21V-961, 24V-118. Open recalls are repaired free at a Mercedes-Benz dealer.

Questions? Ask Springfield Euro Auto at service@springfield-euro-auto.example. The full report, with sources for every figure, is one scan away.

Based on public records and published repair costs. Not a diagnosis or a guarantee. Your technician's inspection decides what your car needs. Confirm recalls with a dealer using your VIN. “If it fails” figures are repair bills reported in public sources or, where none are published, our estimates (each one labeled in the full report); they are not predictions. Open recalls are free at a Mercedes-Benz dealer. Prices are estimates before tax, shop supplies and disposal fees, and may change after inspection. Not a written repair estimate: we confirm the price with you before any work. Data: RepairAhead, 2026-10-27.r1. Not affiliated with Mercedes-Benz Group AG.