SEA

Springfield Euro Auto EXAMPLE SHOP

service@springfield-euro-auto.example

TECHNICIAN WORKSHEET · 9A1/MA1 FLAT-SIX
RA-9A1-123456-20261027

2014 Porsche 911 Carrera · 991 911 Carrera coupe (3.4) · RWD

WP0AA2A91ES123456

ODOMETER IN: 65,000 | DOOR-JAMB BUILD (MM/YY) | RO # | TECHNICIAN / DATE

A · RECALLS AND CAMPAIGNS TO VERIFY (DEALER PRINTOUT OR NHTSA.GOV)

13V-502 · Air bags · passenger seat wiring — ☐ Open ☐ Done ☐ N/A

B · INSPECTION POINTS, IN PLAN ORDER

1. Coolant pipe leak

Watch · Any mileage (911 Carrera (991) model years 2014–2019)

Look for coolant under the engine — ☐ OK ☐ Watch ☐ Fix

Pressure-test — ☐ OK ☐ Watch ☐ Fix

Parts (991): Ask your parts supplier for the OE part number for this VIN.

2. Cylinder bore scoring

Watch · Any mileage (Possible on 997.2 and 991.1; reported far less often than on earlier engines)

Borescope all cylinders — ☐ OK ☐ Watch ☐ Fix

Leak-down test — ☐ OK ☐ Watch ☐ Fix

Borescope: clean / light / scored

Parts (991): Ask your parts supplier for the OE part number for this VIN.

FACTORY MAINTENANCE

Not on this report for this car. Check the service records and the maker's schedule (brake fluid, spark plugs, coolant, transmission fluid). ☐ Records checked ☐ Due ☐ Quoted

C · ALSO REPORTED FOR THE 9A1/MA1 FLAT-SIX, QUICK CHECKS

- **Transmission / PDK** (19 complaints): Counts all transmission complaints; not an engine fault.

NOTES FOR THE ADVISOR

Record findings here (OK / Watch / Fix and measurements); the advisor adjusts the quote before the handout is printed or sent.

Reference only. Follow Porsche repair procedures and your shop's judgment.